



DRX™ 100
dimensions, mounting principle and connection

■ Dimensions




■ Mounting principle




■ Auxiliary contacts


	Voltage (V)	Resistive load (A)
Vac	125	5
	250	5
Vdc	30	5
	50	1
	75	0.75
	125	0.5
	250	0.25
Mechanical endurance (No. of operations)		5 x 10 ⁶
Temperature (°C)		- 40 to 85 °C



Mounting on DIN rail with plate




Fixing on plate



■ Connection

Connection via cable



Connection via busbar

